

A5. Inspection Photographs

Overall ARFF/ Old Terminal Building Apron




ARFF/ Old Terminal Building Apron High Longitudinal/Transverse Cracking



Cargo Apron Small Patch




Cargo Apron High Joint Seal Damage



Commercial Apron Low Alligator Cracking



Commercial Apron Low Longitudinal Crack



Commercial Apron Low Spalling



General Aviation Apron Medium Rutting



General Aviation Apron Low High Longitudinal/Transverse Cracking



General Aviation Apron Oil Spill



Overall South General Aviation Apron

